

Oil Field Environmental Incident Summary

Incident: 20140128134159 **Date/Time of Notice:** 01/28/2014 13:11

Responsible Party: EOG Resources, Inc.

Well Operator: EOG RESOURCES, INC.

Well Name: BURKE 42-3204H

Field Name: PARSHALL

Well File #: 25043

Date Incident: 1/27/2013 **Time Incident:** 14:15

Facility ID Number:

County: MOUNTRAIL

Twp: 155

Rng: 90

Sec: 32

Qtr: NE NW

Location Description:

Submitted By: Luigi Heydt

Received By:

Contact Person: Luigi Heydt
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	barrels	2	barrels	2	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/5/2014

Clean Up Concluded: 1/28/2014

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

The majority of the oil was contained within the treater building itself. The treater is on a skid so the oil was able to be sucked up using a vac truck. The little bit that came out the door of the treater, the snow was picked up and put in a container to be melted and then the water disposed of.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/28/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to treater leak, remained on location, according to the report. NDIC retains oversight. Incident date is most likely 1/27/2014, not 2013.